

Permit Conditions Tracking Report
as of September 22, 2020 - prepared by John Holt

Restoration within east buffer zone – Asher Pit, Harold MacQuinn, Inc

Permit issued October 1, 2013, with required restoration must be completed by September 30, 2016.

Site inspection on November 14, 2016 revealed no restoration undertaken

Hydroseeding done late November, 2016; site to be inspected Spring 2017.

June – CEO inspection finds no restoration present
Planning Board to determine further efforts at restoration

August 7, 2017- PB requested CEO to inform MacQuinn that a new effort at restoration in full compliance of Ordinance requirements needs to be undertaken, and must be completed by September 30, 2017

Sep 20, 2017 – Salsbury informed the town the a different method of hydroseeding has taken place at the pit

Nov 1, 2017 Inspection by CEO and PB chair indicated essential failure of September hydroseeding; pictures taken

Nov 13 – PB requests CEO to send Stop Work Order

Nov 15 – 2nd inspection by CEO and PB Chair indicated some germination of grass seed
To be inspected again by CEO June 2018

Early June 2018 inspection shows significant portions within 100 foot buffer have not been restored at all, while other portions have little successful ground cover from previous hydroseedings.

July 10, 2018 inspection by CEO resulting in Notice of Violation sent by CEO

August 9, 2018 inspection by CEO found that satisfactory sloping and seeding had occurred.
CEO will inspect for vegetative growth mid-September.

Sept 19, 2018 Inspection by CEO and PB Chair found that recently seeded areas are doing well but that a large portion of the southerly end of the of eastern 100-ft buffer has not been vegetated in most areas. MacQuinn agent Steve Salsbury will be notified.

October 3 – restoration as proposed on 2016 application map appears to have been completed satisfactorily. Additional areas on east boundary remained unrestored and may be required during next (2019-2022) permit cycle.

June 12, 2019 – restoration inspected by CEO

Nov 16, 2019 – Site Visit by PB. Consensus that restoration of south portion of 100-foot east setback area needs restoration.

Dec 2, 2019 – New permit issued with additional restoration along east setback area to be completed by September 30, 2020